


Mann House pictures from Bill Newell of Newell & Crathern, January 15, 2019



(1) Foundation areas with air leaks (found many like this)




(2) Foundation areas with air leaks (found many like this)



(4) Foundation areas with air leaks (found many like this)



(5) Foundation areas with air leaks (found many like this)



Hole in area around the chimney in main attic



Insulation above the library



Insulation in the main attic to be removed




Old insulation in attic area



Uninsulated sill beam in the basement



(1) Dark areas show uninsulated wall



(2) Dark areas show uninsulated wall




(3) Dark areas show uninsulated wall




(4) Dark areas show uninsulated wall



(5) Dark areas show uninsulated wall



(6) Dark areas show uninsulated wall



Window without a sash lock



Sash lock is missing



Attic Hatch - Dark area is cold



Attic Hatch to main attic



Air leakage in library



(1) Ceiling and slope Library



(2) Ceiling and slope Library